

Incident Notification

Incident Date: October 9, 2021

Title: **Recordable Radiological Release**

Description: A leak on the tailings thickener underflow pump discharge line caused tailings slurry to be released in the tailings preparation area. Approximately 0.8 m³ of tailings slurry flowed onto the mill terrace.

Resolution: Pumping was stopped and the leak was isolated. Tailings slurry was cleaned up with a vacuum truck and placed back into the tailings circuit. Provincial and federal regulators were notified and a follow-up report will be submitted to regulators.

