

Incident Notification

Incident Date: August 26, 2024

Title: **Dangerous Occurrence – Roofing Screw Contact with Lighting Cable**

Description: While performing roof repairs on the Mill Complex, a screw was drilled through the roof, coming into contact with an electrical cable. This resulted in the breaker being tripped as designed, causing a bank of lights to go out. There were no effects on the environment, health, or safety.

Resolution: Once the cause of the lighting failure was determined, the cable was repaired. Orano has reemphasized to the roofing work team the importance of reviewing and checking the work area for any potential hazards that screws could come into contact with. The regulators have also been notified.

