Incident Notification

Incident Date: May 7, 2025

Title: McClean Lake Operation – Dangerous Occurrence,

Damage to 600V Wire

Description: While an employee was cutting a fiberglass grating to remove a spool of

wire, a 600V electrical cable appeared to be damaged. An electrician was called to do a visual inspection and determined that the cable was intact and safe. When the spool section was removed through the grating, there

was a spark from the cable.

Resolution: A more detailed inspection showed that the cable was damaged. Work

was halted and the area locked out to allow for repair of the damaged cable. No effects on the environment, health or safety. Regulatory

authorities have been notified.

