

Incident Notification

Incident Date: March 4, 2026

Title: Contaminated Slurry Tote

Description: An ore slurry tote shipped from the McClean Lake Operation was received at the Cigar Lake Operation with a visible indication of potential contamination.

Cigar Lake personnel identified a small area of contamination, approximately one centimeter round spot, on the outside of the tote near the top, close to the suction port (the opening where equipment is inserted to remove the uranium slurry). A contamination swipe confirmed the presence of non-fixed contamination above the transport limit of 4.0 Bq/cm².

Resolution: No effects on health, safety or the environment. The slurry tote was immediately cleaned at Cigar Lake and swipe results confirmed an effective cleaning process. A follow-up report will be submitted to regulatory agencies.

